RG104 E-1 Box 177

Mint of the United States at Philadelphia, Pa.,

COINER'S OFFICE,

July 30th, 1892.

Hon A. B. Roosevelt

Superintendent

Sir.

I have the honor to report, that the Arch of No 2 Coining Press is Cracked near the top on the left side, which renders the Press unsafe for use.

This Press is used for Dimes and Cent Coinage, and I would respectfully recommend that measures be taken immediately to procure a new Arch.

Very Respectfully
Your Obt Servant
H Steel

NARA RG104, Entry 1, Box 177

Mint of the United States at Philadelphia, Pa.,
Coiner's Office,
July 30, 1892

Hon. O.C. Bosbyshell
Superintendent

Sir:

I have the honor to report that, the Arch of No. 2 Coining Press is cracked near the top on the left side, which renders the press unsafe for sure.

This press is used for Dimes and Cent coinage, and I would respectfully recommend that measures be taken immediately to procure a new arch.

Very Respectfully
Your Obt. Servant
F.H. Steel